QUALITY CONTROL

BR No: 330

Name of the Work: Providing Development of Slab Drain from 15th Cross to SWD Drain Inside J.P Park in W.No 17 RRN Zone.

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 1 3/4 years back.

Assistant Executive Engineer
Rajarajeshwari Nagar(Project)
Bruhat Bengaluru Mahanagara Palike

Executive Engineer (Project)
Rajajeshwari Nagar Zone
Bruhat Bengaluru Mahanagara Palike